

# G PULLAIAH COLLEGE OF ENGINEERING & TECHNOLOGY, KURNOOL

## DEPARTMENT OF CIVIL ENGINEERING

### Report – Road safety survey

The faculty & students of Civil Engineering Department of GPCET have participated in joint inspection on **Road Safety Survey** on 28/10/2017. Various technical problems have been identified from Nandyal check post (chainage - 6/0) to Kurnool District border (chainage - 96/8). The faculty of CE Dept Mr. **K Mallikarjuna Reddy**, Asst Professor & IV year civil engineering students (**V Kishore Kumar**, **C Purandeswara**, **S Ibrahim**, **M Kishore**, **K Ravi Kumar**) of GPCET were accompanied with officials, Sri. **Sreenivas Rao** Garu (Mortar Vehicle Inspector, Transport Dept), Sri. **Lakshmi Narayana** Garu (SI, Nandikotkur, Police Dept), Sri. **Sudhakar Reddy** Garu (SI, Pamulapadu, Police Dept), Sri. **Venkata Subbaiah** (SI, Atmakur, Police Dept), **Amruth Kumar** (JE, R & B Dept).



Various problems identified along the stretch of road are listed below:

- Extension of culvert near Venkayapalli
- Maintenance of edge shoulders & railing on roads at Bolaravaram.



c) Required to extend the bridge in Nandikotkur

d) Provide shoulders on CC roads near court road, Nandikotkur.



d) Need to clear the jungle beside the roads.



e) Need to provide the approach road speed breakers, sign boards at curves, school zone boards at schools



f) Need to provide the hazard marker boards on bridges & Culverts.



g) Need to maintain the shoulders & road maintenance from 60/6 to 96/8.



The above listed problems brought to the notice for JE, R & B Dept.

Regards

**K MALLIKARJUNA REDDY**  
**Asst Professor, Dept of CE.**